	Туре	L #	Hits	Search Text	DBs	Time Stamp	C o m m e n t s	f i n i t i	Err
1	BRS	L1	151	105/392.5	USPAT; EPO; JPO; DERWEN T	2002/11/05 18:35		n	0
2	BRS	L2	61	105/393		2002/11/05 18:35			0
3	BRS	L3	92	105/402	USPAT; EPO; JPO; DERWEN T	2002/11/05 18:35			0
4	BRS	L4	508	105/410	USPAT; EPO; JPO; DERWEN T	2002/11/05 18:36			0
5	BRS	L5	311	280/784	USPAT	2002/11/05 18:36			0
6	BRS	L6	981	296/181	USPAT	2002/11/05 18:36			0

	Туре	Hits	Search Text	DBs
1	BRS	134	vehicle same body same "end bumper"	USPAT; EPO; JPO; DERWENT
2	BRS	190	105/238.1	USPAT; EPO; JPO; DERWENT
3	BRS	47	105/361	USPAT; EPO; JPO; DERWENT
4	BRS	293	105/396	USPAT; EPO; JPO; DERWENT
5	BRS	459	105/404	USPAT; EPO; JPO; DERWENT
6	BRS	245	105/413	USPAT; EPO; JPO; DERWENT
7	BRS	447	105/423	USPAT; EPO; JPO; DERWENT
8	BRS	123	105/454	USPAT; EPO; JPO; DERWENT
9	BRS	192	105/463.1	USPAT; EPO; JPO; DERWENT
10	BRS	23	105/412	USPAT; EPO; JPO; DERWENT
11	BRS	149	105/452	USPAT; EPO; JPO; DERWENT

	Time Stamp	Comments	ErrorDefinitio	Errors
1	2002/11/04 18:58			0
2	2002/11/04 18:58			0
3	2002/11/04 18:58			0
4	2002/11/04 18:58			0
5	2002/11/04 18:58			0
6	2002/11/04 18:59			0
7	2002/11/04 18:59			0
8	2002/11/04 18:59			0
9	2002/11/04 18:59			0
10	2002/11/04 18:59			0
11	2002/11/04 19:06			0